Navajo Abandoned Uranium Mine

Site Screen Report

This form is for use at the site of abandoned uranium mines (AUM) located on Navajo Nation lands. Applicable sites include all mine and mine features that have or have not undergone reclamation by the Navajo Abandoned Mine Lands Reclamation Program, including features, adits, pits and waste piles. Applicable sites also include all AUM sites listed in the USEPA CERCLIS database, all sites listed in the 2008 AUM GIS Report issued by USACOE and USEPA, all AUM sites on allotment lands associated with the Navajo Nation, and any and all AUM sites not listed in any database located on Navajo lands. Reconnaissance of any sites located on lands adjacent to Navajo lands that may be impacting Navajo lands will need to be coordinated with the authorities appropriate to those lands.

The purpose of the form is to ascertain the status and location of the identified AUM site, and record all immediate site information associated with the mine site. Decisions and recommendations on what additional steps are needed will be provided on a separate document.

H. B. Roy No. 2 AUM Site

Navajo AUM Northern Region

Prepared by:

Weston Solutions, Inc.

Contract: W91238-06-F-0083

12767.063.496.1111

March 2010

Part I	Site Identification, Location and Status						
Site Names and ID numbers as applicable							
Mine ID:	407						
Map ID:	N284						
CERCLIS:	NNN000908875						
Navajo Abandoned Mine Land Reclamation Program: None							
Local name / Aliases: H. B. Roy 2							
Chapter and local area: Sanostee Chapter							
County: San	Juan State: New Mexico						
Lat/Long: 36.3922590416 N / -109.007955882 W							
Nearby road	and highway: Indian Route 5010 Local Post Office: Sanostee, NM						
Surface Land Status: check one or more and provide ownership and contact information below							
Tribal Trust l Private Bureau of La State	Tribal Fee Land						
Subsurface Mineral Rights:							
The mineral rights ownership was identified as Indian.							
Claim and operator information:							
The mine site surface land status is classified as Tribal Trust Land. Historical documents showed the operator of the mine as Bigler and Johnson in 1954. No other historical ownership / lease information was identified in the EPA/AUM database.							
Number of residential structures within 200 feet of mine:							
None							
Estimated vol	Estimated volume of mine waste onsite:						

Unknown

Part II Summary of radiological readings

Highest gamma radiation measurement:

None

Describe any other radiological measurements:

Weston was unable to access the site, all known paths to the site were impassible. A site map is represented in Figures 1.

Background Locations

Average background = None

None

Distribution Chart and Statistics:

None

Part III Status of Reclamation and Mine Waste

The following information was obtained from the Navajo Abandoned Mine Land Reclamation Program (NAMLRP) Point Features Database:

NAMLRP Status of the mine site: Reclaimed: No Waste Pile onsite: Yes

NAMLRP Project Number: None

NAMLRP Mine features: 3 Rim Strip / Pits

The following information was obtained from field observations collected during the 2009 site screening:

Provide description and status of all mine sites and features at site. Include all waste piles, adits, pits and other features, and indicate whether they are open, closed, covered, capped, buried or unreclaimed. Indicate approximate size, shape and extent, including description of any reclamation caps. Note condition of all caps.

(Observed	reclan	nation	work	and	ctatus
•	msei veu	TECIAII	IALIOII	WUIK	anu	SIALIS

Adits

Unknown

Waste Piles

Unknown

Pits

Unknown

Shafts

Unknown

Other Debris and Mine Features

The site was inaccessible, therefore no other mine features were observed during the site visit.

Part IV

Site observations and Environs

Observed Structures: list number of and describe human habitation status of structures at the following distances from mine:

0 to 200 feet: None

200 feet to 0.25 mile: None

Observed Public or commercial structure: list and describe all schools, clinics, Chapter Houses, places of business and any other structure used by members of the community at the following distances:

0 to 200 feet: None

200 feet to 0.25 mile: None

Levels measured around the perimeter(s) of the identified structure(s):

None

Observed water sources: list the number and type of wells and surface water sources that are potentially used for human consumption at the following distances from the mine:

0 to 0.25 miles: None

0.25 miles to 4 miles: None

Sensitive environments: note and describe all sensitive environments located within visible range of the mine site, including: wetlands, endangered species, habitats and approximate locations of sites that may be under protection of the government of the Navajo Nation.

None observed

Known Site History: include information from interviews with Chapter officials and residents. Note information on mine ownership, type of mining operation, period of operation, known amount of production, and any other information as provided.

H.B. Roy No. 2 mine consists of an area of 54,398.93 m². The mine was identified as being operational in 1954. Historical documents showed the operator of the mine as Bigler and Johnson in 1954. While operational, the mine had a total reported production volume of 6 tons. No other historical information or any additional ownership / lease information was identified in the EPA/AUM database.

Part V Response Action Summary

Site Name(s): H.B. Roy No. 2 **Chapter:** Sanostee

Decision Criteria

Is there an unreclaimed waste pile at the site? Unknown

At what distance from the waste pile is the nearest residential structure located? None

At what distances from the waste pile are there potential drinking water sources? None

Is there a reclamation cap or sealed adit in place at the site? Unknown

Is the cap/seal functionally intact? Unknown

Is the cap/seal sufficiently degraded to create a concern about releases? Unknown

At what distance from the cap/seal is the nearest domestic structure located? None

At what distance from the cap/seal is the nearest domestic drinking water source? None

Summary of emergency response factors

None

Summary hazard ranking system factors

None

Summary of reclamation factors

Unknown

Part VI Photos



Photo 1. Direction towards mine site

Part VII Contacts Reports and Information

Name:	<u>Stanley Edison</u> (928) 871-6861						
	Eugene Esplain (928) 871-7331						
Title or official role (if any) Navajo EPA Superfund Program							
Address PO Box 2946, Window Rock, AZ 86515							
Information provided <u>Lead Regulatory Agency</u>							
Name							
Title or of	fficial role (if any)						
Address_							
Telephone	e number						
Information	Information provided						
Name							
Title or of	Title or official role (if any)						
Telephone number							
Information provided							
Name							
Title or of	_						
Telephone	_						
Information	on provided						



